bernette

Firmware Release Notes

BERNINA International AG · Seestrasse 161 · CH-8266 Steckborn

Firmware Version

- b70: V15.56
- b79: V15.76

Note: The new firmware version for the b79 is also made for the b79 Yaya Han Edition.
Please note, that on a b79 Yaya Han Edition no firmware version prior to V11.3 may be installed.
Doing so, will delete the special Yaya Han designs from the machine.
In the unfortunate case that this has been done you can still download the special Yaya Han designs form our portal after registering your machine.

Table of contents

Firmware Version 1
Release Notes 2
1. General 2
1.1. Initializing of thread tension stepper motor improved (b70, b79) 2
1.2. SD Card and IO Board compatibility (b70, b79) 2
Previous versions 2

Release Notes

1. General

1.1. Initializing of thread tension stepper motor improved (b70, b79)

The initializing procedure of the tension stepper motor has been improved to solve the issue that the thread tension discs don’t close when the presser foot button is pressed after starting the machine. With previous versions the discs would not close if the machine had not yet sewn or embroidered.

1.2. SD Card and IO Board compatibility (b70, b79)

The SD Card – IO Board compatibility has been improved to prevent cases of machines not turning on. This improvement is only effective for new machines. Updating a machine with the issue will not solve the issue.

Previous versions

- b70: 1.22, 2.25, 3.28, 5.34, 6.36, 7.41, 8.43, 9.49, 10.51, 12.52, 13.54, 14.55
- b77: 1.15, 2.17, 3.24, 5.28, 6.32, 7.38, 8.40, 9.46, 12.49, 13.53
- b79: 1.26, 2.31, 3.38, 5.45, 6.49, 7.56, 8.59, 9.65, 10.67, 11.3, 12.70, 13.74, 14.75